




45x90
(p. 2-41)



45x90




45x90L
45x90L 2N
45x90L 3NVS
(p. 2-40)




19585

45x90L




00109731


45x180
(p. 2-41)




45x180




90x90L
90x90L 4N
90x90L 4NVS
(p. 2-43)



90x90L




90x180L
(p. 2-45)



19588

90x180L



00109734

Air-supply elements

- ▶ Rexroth **strut profiles** can be used as compressed-air leads and reservoirs. The hollow chambers or central holes are used
- ▶ **Flanged plate** for end closing of profiles (p. 5-3)
- ▶ Compressed-air intake or discharge at the flanged plate, **connection piece**, or **connection screw fitting** (p. 5-4)
- ▶ Air-tight connecting of profiles with **longitudinal end connectors or T-connectors** (p. 5-6, 5-5)
- ▶ The use of the heavy-duty profiles is preferable in the case of more demanding leak-tightness requirements (e.g. for underwater applications)